



1/11

FIG. 1



2/11

FIG. 2



00621" 99252/50

3/11

FIG. 3






FIG. 7





5/11


FIG. 5



005221 993400


6/11

FIG. 6




09725366-12900

7/11



8/11


FIG. 9



0052526460



FIG. 10



DETECTION OF P CHANNEL  
OF RECEPTION OF SKIP COMMAND

SEARCH  
(DISC CHANGE)  
BOOT

SOUND MATCHING

FIG. 11A

READ FROM HDD  
(WRITE IN BUFFER MEMORY B9)

track b  
(A0 ~ A(n-1))

FIG. 11B

OUTPUT FROM ATTENUATOR B15

track b

FIG. 11C

READ FROM CD1  
(WRITE IN BUFFER MEMORY A8)

track b  
(An~)

FIG. 11D

OUTPUT FROM ATTENUATOR A14

track a

track b

FIG. 11E

OUTPUT FROM ADDER 11  
(AUDIO DATA)

AUDIO DATA  
FROM CD1  
track a

AUDIO DATA  
FROM HDD 10  
track b

AUDIO DATA  
FROM CD1  
track b

FIG. 12E  
AUDIO DATA